



DRM MOTORS



2023-73 | SUZUKI SX4 S-CROSS

MOTION BOOSTERJET MHEV | Hybrid | Manual | BLACK



<https://www.drm-motors.co.uk>
01754 767131



Price	£13,750
Engine Size	1.4
Fuel Type	Hybrid
Transmission	Manual
Body Type	Hatchback
Number of Seats	5
Number of Doors	5
External Colour	BLACK
External Paint	Metallic
Tab Band	£200
Mileage	18,499 miles
Registration	KS73RDV
Registered	20/11/2023
Insurance Group	22A

SPECIFICATIONS

Hill hold control	Rear parking camera	Automatic headlamp levelling
12V accessory socket in luggage area	Keyless entry and start	2 Tweeters
Emergency flat tyre repair kit	Front passenger airbag deactivation	Intelligent speed assist
Rear fog lamp	Shift knob piano black with chrome accent	Immobiliser
DAB Digital radio	17" Painted alloy wheels	ESP
Engine auto start/stop system	Wheel arch extensions	Rear centre armrest
Security alarm	Steering wheel mounted audio controls	Side airbags
Driver monitoring system	Chrome effect window sills	Pollen filter
Light - on and Key in reminder	4 speakers	3 Point ELR rear seat belts x3
Blind spot monitor	Rear side wing doors	2x Front and rear door bottle holders
Remote central door locking	USB connection	Childproof rear door locks
Emergency stop signalling system	Heated door mirrors	ISOFIX child seat anchorages X 2
Deadlocks	Side impact protection beams	Lane departure warning system
Visible VIN plate	Glovebox light	Freewheeling key cylinders
Traction control	Bluetooth integrated into audio unit	LED rear combination lamp

TECHNICAL

Performance	
0-100 kmh (62 mph)	9.5 s
Top speed	121 mph
Power	129 bhp
Torque	235 Nm
Fuel Consumption Ice	
MPG (combined)	52.3 mpg
L/100km (combined)	5.4 l/100km
Vehicle Dimensions	
Length	4300 mm
Width	1785 mm
Capacities	
Seats	5
Boot (seats up)	430 litres
Boot (seats down)	665 litres
Fuel tank	47 litres
General	
Trim	Motion
Power (PS)	129

01754 767131

dean@drmmotors.co.uk

DRM Motors Beresford Avenue Skegness Lincolnshire PE25 3JD

Whilst every effort has been made to ensure the accuracy of the vehicle specification, some inaccuracies may occasionally occur. It is important that you do not rely solely on this information, but check with a member of the sales staff about any features which may affect your decision to buy the car.